

0730Z 24 JAN 63

SECRET

DIRECTOR

25X1A

OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

PRIORITY

S/C (17)

25X1A

TOR: 0039Z 25 JAN 63

25X1A

IN 63727

PRITY

2916

25X1A

25X1A

1. G-3215/11400/
2. 9R/0-11-6000/189-10-2-6-2/9L/0-11-6000/189-2-10-62
3. D-19/4/79DEGREES/HTA/2.
4. 2.3
5. GOOD TO HEAVY/LOW TO HIGH/POOR/SEE PARA 6
6. TAKE RECEIVED AT 0755Z 23 JAN IN COVERED STEEL BOXES. CONDITION GOOD. VACUUM FAILURE VARIABLE 3 TO 7 INCH RADIUS FROM CENTER OF PLATEN, BEGINNING AT FRAME 0290 AND GETTING PROGRESSIVELY WORSE. RESOLUTION NEAR INNER EDGE EXTREMELY POOR ON BOTH 9R AND 9L, ALL POSITIONS. LOSS OF VACUUM EXTENDS TO WITHIN 1 AND ONE HALF INCH OF OUTER EDGE ON SOME FRAMES. EVIDENCE OF IMAGE MOTION IN DATA CHAMBER DURING EXPOSURE. READIBILITY OF FRAME NUMBERS VARIES FROM DIFFICULT TO UNREADABLE BEGINNING AT FRAME 0290. VACUUM FAILURE HAS SAME GENERAL PATTERN AS REPORTED IN

FOR

25X1A

SECRET

25X1A

25X1A

25X1A

25X1A

S E C R E T 25X1A

[] 2916 (IN 63725)

PAGE TWO

[] MISSION DATA SHEET DOES NOT REPEAT NOT INDICATE []
SER NR. IS CONE SER NR SAME AS CONF SER NR? [] WILL
PROCESS TEST [] GN 63-02 AS SOON AS WRAP UP IS COMPLETED ON
6-3215 AND WILL REPORT BY [] OPS IMMED.

7. NOT ACCOMPLISHED.

25X1A

8. EST DEPARTURE OF HQS COURIER WITH [], IS 1900 LOCAL 25
JAN 63.

END OF MESSAGE

25X1A

25X1A

S E C R E T